File Ed	lit Vie	2W	Navigate	Project	Run	Scripts	Window		
🖻 🕶 🛛) F	Resource Explorer						
Project) F	Resource Explorer Offline						
	ect 🚳) (Getting Start	ed					
1 a	PP 💔	0	CCS App Cer	iter					
📋 В	oc 🕞	0	GUI Compos	er™			>		
E E	xar 🕞) minut Eurole						
E F	280 💷		roject explo	brer		A.I CI	10 - O - Y		
	283 📷		roblems			Alt+Si	hiπ+Q, X		
> <u>}</u> (≅ E	283		Console			Alt+Sł	hift+Q, C		
> 🚝 fl	asl 🖓	4	Advice						
📋 fl	ast 🕸	: [Debug						
📋 fl	ast 📋	N	Memory Bro	wser					
		î F	Registers						
	କୁଟ୍	' E	xpressions						
	(×)=	• ۱	/ariables			Alt+Sł	nift+Q, V		
	-	1	Disassembly						
	•	E	Breakpoints			Alt+Sł	nift+Q, B		
	=		Nodules						
	\$	1	erminal						
	(ja	1	Ceripting Co	nsole					
		1	arget Config	gurations	>				
	-	C							

😚 TEST - flash_programming_cpu01/flash_programming_cpu1_FLASI

Target Configurations ウィンドウから、デバイスに接続するための ccxml ファイルを選択し、右クリックから"Launch Selected Configuration"を選択します。



デバッグパースペクティブに切り替わりますので、接続する CPU を選択し、右クリックから"Connect Target"を選択し、デバイスに 接続します。

窷 TEST - flash_programming_cpu01/flash_programming_cpu1_FLASH.cmd - Code Composer Studio								
File Edit View Project Tools Run Scripts Window Help								
📑 🕶 🔚 🐚 🖳 🕪 💷 🔳 🔍 🖘 Let 🖽 🖳 🎭 🖉 🕶 🚱 🛸 🗸	5 💣 ▾ 🐎 ▾ 🔍 👁 🐔 ▾							
☆ Debug ☆								
 Texas Instruments XDS100v2 USB Debug Probe_0/C28xx_CPU1 (Disconnected version of the second se	Connect Target Disconnect Target Enable Global Breakpoints							

続いて"Tools → On-Chip Flash"を選択し、On-Chip Flash ウィンドウを開ききます。

File	Edit	View	Project	Tools	Run	Scripts	Window	Help	
1	• 🗐		9 i 📭 🛛	\bigcirc)n-Chij	p Flash			
☆D	ebua	23		C)ebugg	er Option	IS	>	

😚 TEST - Source not found. - Code Composer Studio